School Facility Needs 2019 to 2022 and Beyond - School Buildings												
Requests: Items to Budget	First three years								ne figures show current mark		timates based Beyond 2022	
Mansfield Middle School	2	2019/2020	2020/2021				2021/2022		Priority One		P	riority Two
(Excluding Portables)												
Carpeting Upgrades	\$	15,000.00	\$	10,000.00		,	10,000.00					
Electrical System Upgrades											\$	440,000.00
Exterior Door Replacement	\$	20,000.00	\$	20,000.00		,	20,000.00					
Facility Study (Renovations)			\$	200,000.00	*							
Folding Divider Walls Rms 99/100, 104/105, 203/204, 308/309 Replace	\$	25,000.00	\$	25,000.00		,	25,000.00	\$	30,000.00			
Generator Upgrade Replacement			\$	150,000.00								
Install Sprinkler System best practice only											\$	840,000.00
required when doing major renovations \$7 per												
sq. Ft.												
Kitchen Upgrades (Exhaust for Dishwasher)	\$	25,000.00									\$	150,000.00
New Elevator (ADA Compliant)								\$	250,000.00			
Outside Transite Soffit Replacement											\$	300,000.00
Demolition of Portable Classrooms								???				
Renovate Art Room								???	·			
Replace Electric Hot Water Heaters with On Demand Heating			\$	25,000.00		5	25,000.00					
Replacement of Auditorium (Air Conditioning)						,	150,000.00					
Roof Replacement, Upkeep / Repairs	\$	10,000.00	\$	260,000.00	§	(2,500,000.00					
Room Cabinet / Counter Replacements	\$	35,000.00	\$	35,000.00		9	35,000.00	\$	35,000.00		\$	35,000.00
Schools Clock system (Master Clock)			\$	45,000.00								
Sealing of Brick Veneer			\$	15,000.00		,	15,000.00	\$	15,000.00			
VCT Floor Tile 90,000 sq. ft at \$3 per foot								\$	270,000.00			
Window Replacements								\$	450,000.00	**		
Building Sub Totals:	\$	130,000.00	\$	785,000.00		0	\$ 2,780,000.00	\$	1,050,000.00		\$	1,765,000.00
Goodwin School	2	2019/2020		2020/2021			2021/2022	P	riority One		P	riority Two

Bathroom ADA Modifications and Upgrades								\$	250,000.00
Bulk Head for Tunnel (Confined Space)			\vdash		1			\$	40,000.00
Cafeteria pocket tables			\vdash		\$	45,000.00		Ş	40,000.00
Electrical System Upgrades			\vdash		Ş	45,000.00		\$	220,000.00
Exterior Door Replacement			\vdash		\$	60,000.00		Ą	220,000.00
Fresh Air Ventilation (Air Conditioning)			\vdash		Ş	60,000.00		\$	775,000.00
Generator Upgrade Replacement			\vdash		\vdash			\$	100,000.00
HVAC / Heating Control Upgrade			\vdash		1			\$	100,000.00
Install Sprinkler System best practice only			\vdash		1			\$	245,000.00
required when doing major renovations \$7 per								۲	243,000.00
sq Ft.									
Insulation Upgrades			\vdash		1			\$	100,000.00
Kitchen Upgrades / Replace Grease Trap			\vdash		1			\$	150,000.00
Move Office Proximity Near Main Entrance					???)		<u> </u>	130,000.00
Outside Transite Wall Replacement								\$	500,000.00
Plumbing piping replacements					??	?			
Repair / Replacement Paved Play Area								\$	18,000.00
Replace Gym Partition								\$	50,000.00
Replace older Boiler					\$	100,000.00			
Roof Replacement and Upkeep	\$ 7,000.00	\$ 7,000.00		\$ 7,000.00	\$	1,050,000.00	**		
Room Cabinet / Counter Replacements								\$	50,000.00
Sealing of Brick Veneer					\$	30,000.00			
Septic System								\$	80,000.00
VCT Floor Tile and Carpeting		\$ 7,000.00						\$	90,000.00
Window Replacements							**	\$	450,000.00
Building Sub Totals:	\$ 7,000.00	\$ 14,000.00		\$ 7,000.00	\$	1,285,000.00		\$	3,218,000.00
Southeast School	2019/2020	2020/2021		2021/2022		Priority One			Priority Two
	,	,		,		,			•
Bathroom ADA Modifications and Upgrades								\$	250,000.00
Bulk Head for Tunnel (Confined Space)								\$	40,000.00
Cafeteria pocket tables					\$	45,000.00			
Electrical System Upgrades		1	-		_		_	\$	220,000.00

Exterior Door Replacement							\$	60,000.00			
Fresh Air Ventilation (Air Conditioning)										\$	775,000.00
Generator Upgrade Replacement										\$	100,000.00
Gym Floor Replacement										\$	50,000.00
Heating System Upgrades/Replacement		\$	50,000.00	€			\$	550,000.00	+		
HVAC Control Upgrade										\$	100,000.00
Include space in Portables into the School										???	
Building											
Install Sprinkler System best practice only										\$	245,000.00
required when doing major renovations \$7 per											
sq. Ft.											
Insulation Upgrades										\$	100,000.00
Kitchen Upgrades / Replace Grease Trap										\$	150,000.00
Move Office Proximity Near Main Entrance							???				
Outside Transite Wall Replacement										\$	600,000.00
Plumbing piping replacements							???				
Repair / Replacement Paved Play Area										\$	18,000.00
Replace Gym Partition										\$	50,000.00
Roof Replacement and Upkeep	\$ 7,000.00	\$	7,000.00		\$	7,000.00	\$	900,000.00	**		
Room Cabinet / Counter Replacements										\$	50,000.00
Sealing of Brick Veneer							\$	30,000.00			
Septic System							\$	80,000.00			
VCT Floor Tile and Carpeting										\$	90,000.00
Window Replacements									**	\$	450,000.00
		1			1					1	
Building Sub Totals:	\$ 7,000.00	\$	57,000.00		\$	7,000.00	\$:	1,665,000.00		\$	3,288,000.00
Building Sub Totals: Vinton School	7,000.00 19/2020		57,000.00 020/2021			7,000.00		1,665,000.00 riority One			3,288,000.00 riority Two
			•			·				P	
			•			·					
Vinton School			•			·				P	riority Two
Vinton School Bathroom ADA Modifications and Upgrades			•			·				P	250,000.00
Vinton School Bathroom ADA Modifications and Upgrades Bulk Head for Tunnel (Confined Space)			•			·	P	riority One		P	250,000.00

Fresh Air Ventilation (Air Conditioning)								\$ 775,000.00
Generator Upgrade Replacement								\$ 100,000.00
Gym Floor Replacement								\$ 50,000.00
HVAC Control Upgrade								\$ 100,000.00
Install Sprinkler System best practice only					\$	245,000.00		
required when doing major renovations \$7 per								
sq Ft.								
Insulation Upgrades								\$ 100,000.00
Kitchen Upgrades / Replace Grease Trap								\$ 150,000.00
Outside Transite Wall Replacement								\$ 500,000.00
Plumbing piping replacements					??′	?		
Renovations of the Back Building					??	?		
Repair / Replacement Paved Play Area								\$ 18,000.00
Replace Gym Partition								\$ 50,000.00
Roof Replacement / Upkeep	\$ 7,000.00	\$ 7,000.00	\$	7,000.00	\$	900,000.00	**	
Room Cabinet / Counter Replacements								\$ 50,000.00
Sealing of Brick Veneer					\$	30,000.00		
Septic System								\$ 80,000.00
VCT Floor Tile and Carpeting			\$	7,000.00				\$ 90,000.00
Window Replacements							**	\$ 450,000.00
Building Sub Totals:	\$ 7,000.00	\$ 7,000.00	\$	14,000.00	\$	1,280,000.00		\$ 3,023,000.00
Grand Totals:	\$ 151,000.00	\$ 863,000.00	\$	2,808,000.00	\$	5,280,000.00		\$ 11,294,000.00

architect. The estimate is 10% of the projected full cost.

^{*} Pending decision on Elementary Schools
Project
§ For MMS Roof this estimate is for an
architect. The estimate is 10% of the project

^{**} Any budget item relating to windows or roofing may increase in estimate after sampling for hazardous materials

€ For Southeast heating system an above ground oil tank can be added to keep current boilers running.

† For Southeast, a future decision will need to be made on converting the system to an energy efficient system. Reflected in the \$550,000.00 costs.